


LEGEND

-  Existing Dike
-  Existing Spur Dikes
-  1939 Right Bankline
-  1939 Left Bankline

This aerial image was not digitally orthorectified and the scale varies by several percent across the figure. 1939 banklines drawn are a close approximation of their actual location relative to the 1996 bankline as seen in this figure. Location of dikes are also estimates of actual locations.

1000 0 1000 2000 3000 4000 Feet

**Figure 3. Change in Banklines: 1939-1996
Matanuska River near Palmer, AK**

**Expedited Reconnaissance Study 905(b)
Matanuska River Erosion**